


# Problems Previously Identified in the IH 35 PEL Study Area (Exhibit 3)



**Please place a green dot next to the items that you believe are problems, and a red dot next to those that you do not believe are problems.**

Increased traffic in Brooke Army Medical Center area	
Choke points located along the corridor	
No good alternative routes to IH 35 because of at-grade rail crossings on arterials	
Lack of connecting facilities or capacity on connecting facilities to IH 35	
Not enough emphasis on mixed use development in the corridor	
Not enough transit coverage or options in the corridor	
Inadequate storage for both exit lanes and merging lanes.	
Accident clearance policies (fire trucks as first responders and jurisdictional confusion) contribute to peak-hour back-ups.	

Less **time** in traffic

More **time** for you

It's **time** to take action



[www.TimeFor35.com](http://www.TimeFor35.com)

